












OPTIMISATIONS BROUGHT ON RIBAMBELLE & RIBAMBELLE XL

Identified issues	Solutions	Visual
Vertical gap between table top and extensions	<ul style="list-style-type: none"> - Increase height of the pads - Creation of tools helping the control - Accepted tolerance of 1 mm max 	
Horizontal gap between table top and extensions	<ul style="list-style-type: none"> - Revue of the pegging tools - Creation of tools helping the control - Modification of the indexing finger - Accepted tolerance of 1 mm max 	
Scratches on the extensions	Moving the keeper	
	Change of the washer's shape	
	Changes of the pads design	
	<ul style="list-style-type: none"> - Addition of sticker pour facilitate the extensions manipulation - Adjusted notice 	

OPTIMISATIONS BROUGHT ON RIBAMBELLE & RIBAMBELLE XL

Identified issues	Solution	Visual
Difficulties in differentiating the extensions	Sticker under the central extension	
Paint issues on the extensions	Addition of plastic stops at the end of the storage unit	
Keeper damages	Addition of holes in the keeper support tube allowing its replacement	
	Creation of an after-sales kit	
Possible water stagnancy in the box and on the table top	Addition of the table's block	 
Leg Comfort at the end of the table	Modification of the storage unit's shape	